


1971 CJ-5 V-6 WIRING DIAGRAM, ENGINE AREA



**NEW 1971 CJ-5 FUSE BDX
TOP OF BDX**

1	FROM IGN	20 AMPS	C	TURN SIGNAL,
2	FROM BAT	30 AMPS	I	HEATER
3			H	SPARE
4			A	HEAD LIGHTS
5	BAT TO IGN SW	30 AMPS	F	CIGAR LIGHTER
6	TO HORN	15 AMPS	B	4 WAY FLASHER, BRAKE LIGHTS
7	TO BRAKE SW	25 AMPS	D	HORN
8	TO 4 WAY FLASHER	30 AMPS	E	IGN SWITCH
9	TO TURN SIGNAL			
10	TO TURN SIGNAL			
11				
12				
13				

